


EVOLUTION E2 BENCH PARTS

You should have:



ITEM	Quantity x Size in Cm				
	60950 EB160	60951 EB210	60952 EB260	60953 EB310	60954 EB360
Beam A (Front to back) PJ32/001	4x125	6x125	6x125	6x125	6x125
Beam B (Side to side) PJ**/001	3x182 PJ28	6x114 PJ05	6x139 PJ29	6x164 PJ30	6x189 PJ31
Leg PH06/001	4 x 87	6 x 87	6 x 87	6 x 87	6 x 87
Bench Edge Extrusion KB**/100	1x182 KB22	2x114 KB23	2x139 KB24	2x164 KB25	2x189 KB26
LH Bracket CA10/427	1	1	1	1	1
Centre Bracket CA10/428	0	1	1	1	1
RH Bracket CA10/426	1	1	1	1	1
Fixing Block KB22/101	2	2	2	2	2
End Fixing Screws CA30/323	4	4	4	4	4
Base Bracket Screws CA30/016	8	10	12	14	16
Joining Bracket PK01/001	16	28	28	28	28
Grub Screw CA30/199	48	84	84	84	84
Worktop Fixing PC11/100	6	11	11	11	11
Long Screw CA30/255	6	11	11	11	11
Height Adjuster PP01/000	4	6	6	16	6
4mm Hexagon Wrench CA25/114	1	1	1	1	1
Spacer PJ99/001	1	1	1	1	1
4mm Hexagon Driver Bit CA25/320	1	1	1	1	1